

INSPECTION REPORT


End of contract

GENERAL INFO

File	307332
License plate	2DRS181
Vehicle identification number	VR3FRHNSLPY556552
Dossier	2022 188 207
Make	Peugeot 308 SW 1.2 130 Active
Mileage	25938
First registration	06/06/2023
client availability date	04/03/2026
inspectionDate	12/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	N
104	Door Rear Left // Repair & Painting	N
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
14	Bumper Front // Repair & Painting	N
35	Front Bonnet // Polish	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
107	Door Rear Left / Trim / Replace	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
165	Roof // Polish	Y
174	Light / Rear Right / Replace	Y
180	Wing Rear Right // Smart Repair Small	N
203	Rocker Panel Right // Repair & Painting	N
533	Trunk Compartment / Side Cover Right / Replace	Y
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Damage within Renta-norm-scratch



Rocker Panel Right // Repair & Painting-dent



Trunk Compartment / Side Cover Right / Replace-dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Small-scratch + dent



Side View Mirror Left / Direction Indicator / Replace-cracked




Front Bonnet // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch





Dashboard // Repair-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch



Roof // Polish-scratch



Door Rear Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch





Door Rear Left // Repair & Painting-scratch + dent



Wheel Alloy Front Right // Repair-scratch



Tyre Front Right // Replace-tear