

INSPECTION REPORT

End of contract

GENERAL INFO

File	310527
License plate	2BCR241
Vehicle identification number	TMBJB7NS6M8039782
Dossier	2021 260 036
Make	Skoda Kod.1.5TSI 110kW Clever
Mileage	68191
First registration	01/10/2021
client availability date	20/04/2026
inspectionDate	30/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
117	Wing Rear Left / Trim / Replace	N
156	Rear Bonnet // Polish	Y
194	Door Rear Right // Repair & Painting	N
222	Side View Mirror Right // Painting	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
543	Interior // Ionization Odor	N
548	Interior / Side Cover / Replace	N
551	Central Console // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-



Side View Mirror Left // Painting-scratch




Wing Rear Left / Trim / Replace-scratch



Rear Bonnet // Polish-scratch



Side View Mirror Right // Painting-scratch



Door Rear Right // Repair & Painting-scratch + dent



Interior // Repair 2-Incinerated



Interior // Repair 1-Incinerated



Interior / Side Cover / Replace-Incinerated



Central Console // Repair-Incinerated



Interior Cleaning // Small-stain