

INSPECTION REPORT

End of contract

GENERAL INFO

File	319972
License plate	2BTD842
Vehicle identification number	W1K2062031F049833
Dossier	2021243026
Make	Mercedes C Break 200 d 120kW A
Mileage	106059
First registration	14/03/2022
client availability date	13/08/2026
inspectionDate	24/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	Y
41	Windshield // Replace	N
100	Door Rear Left // Smart Repair Small	N
136	Bumper Rear // Polish	Y
150	Rear Bonnet // Smart Repair Small	Y
233	Wing Front right // Painting	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y



Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Painting-scratch




Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Rear // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet // Smart Repair Small-dent



Windshield // Replace-cracked