

INSPECTION REPORT

End of contract

GENERAL INFO

File	313436
License plate	2BQG413
Vehicle identification number	W1N2539131V347168
Dossier	2021258016
Make	Mercedes GLC 200d Bus.Sol.
Mileage	188261
First registration	14/02/2022
client availability date	27/05/2026
inspectionDate	04/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
133	Bumper Rear // Painting	N
187	Wing Rear Right / Trim / Replace	N
13	Bumper Front // Painting	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
83	Door Front Left // Painting	Y
103	Door Rear Left // Painting	Y
153	Rear Bonnet // Painting	N
181	Wing Rear Right // Smart Repair Medium	N
191	Door Rear Right // Smart Repair Medium	N
193	Door Rear Right // Painting	Y
213	Door Front Right // Painting	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Bumper Front // Painting-scratch



Rear Bonnet // Painting-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Smart Repair Medium-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Smart Repair Medium-scratch




Wing Rear Left / Trim / Replace-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch



Bumper Rear // Painting-scratch