

INSPECTION REPORT

End of contract


GENERAL INFO

File	315583
License plate	JV5914
Vehicle identification number	VR3USHN5SNJ662328
Dossier	2021342058
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	72494
First registration	28/07/2022
client availability date	17/06/2026
inspectionDate	19/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
184	Wing Rear Right // Repair & Painting	Y
233	Wing Front right // Painting	Y
282	Bumper Rear / Trim Center / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Front Bonnet // Painting-scratch




Wing Front right // Painting-scratch




Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-cracked



Interior Cleaning // Small-stain



Bumper Front // Painting-stone chipping