

INSPECTION REPORT

End of contract

GENERAL INFO

File	316905
License plate	WY5544
Vehicle identification number	YV1UZZK5V4P1197356
Dossier	2022026004
Make	Volvo XC60 B4 197 MHEV Plus Br
Mileage	130649
First registration	21/06/2022
client availability date	01/07/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	N
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Bumper Rear / Trim Center / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent