

INSPECTION REPORT



End of contract

GENERAL INFO

File	320015
License plate	2BGF325
Vehicle identification number	VF3MCYHZMMS228104
Dossier	2021 098 088
Make	Peugeot 5008 1.5BHdi 96kW GT
Mileage	91631
First registration	15/11/2021
client availability date	19/08/2026
inspectionDate	21/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
38	Front Bonnet / Insulation / Replace	N
78	Side View Mirror Left / Direction Indicator / Replace	N
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y
850	Certificate of Conformity //	N
851	Registration Card loss Arval name //	N
883	Key Price Range 2 //	N


Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch




Bumper Front // Painting-scratch



Rear Right Door Interior Coating // Replace Completely-scratch




Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Wing Rear Right // Polish-scratch



Rocker Panel Left // Smart Repair Medium-dent




Rocker Panel Right // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Interior // Repair 1-bad repair



Door Front Left // Painting-bad repair



Wing Rear Left // Painting-bad repair



Bumper Rear // Painting-bad repair



Front Bonnet / Insulation / Replace-cracked



Trunk Compartment / Boot Cover / Replace-missing