

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309083
License plate	2BQA380
Vehicle identification number	KMHC851CGNU278554
Dossier	2021 307 054
Make	Hyundai Ioniq 1.6Di Hybride F
Mileage	149743
First registration	10/02/2022
client availability date	27/03/2026
inspectionDate	03/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	N
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
72	Side View Mirror Left // Painting	N
80	Door Front Left // Smart Repair Small	N
87	Door Front Left / Trim / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
174	Light / Rear Right / Replace	Y
216	Door Front Right // Polish	Y
217	Door Front Right / Trim / Replace	N
236	Wing Front right // Polish	Y
272	Bumper Front / Trim Right / Replace	Y
311	Wheel Alloy Front Left // Repair	N
326	Tyre Rear Left // Replace	Y
331	Wheel Alloy Rear Right // Repair	N
336	Tyre Rear Right // Replace	Y
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
421	Seat Front Right // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N
773	Interior / A Pillar Lower Cover / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Door Front Right / Trim / Replace-Chemical reaction



Door Front Left / Trim / Replace-Chemical reaction



Tyre Rear Left // Replace-tear



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain



Tyre Rear Right // Replace-worn



Bumper Front / Spoiler / Replace-stone chipping



Bumper Front / Trim Right / Replace-stone chipping



Bumper Front // Painting-stone chipping



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Front right // Polish-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Dashboard / Steering Wheel / Replace-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Door Front Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wheel Alloy Rear Right // Repair-scratch



Door Front Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch




Door Rear Left // Polish-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Repair & Painting-scratch + dent