

INSPECTION REPORT

End of contract

GENERAL INFO

File	311269
License plate	2ASC980
Vehicle identification number	VR3FBYHZTMY510382
Dossier	2021 032 010
Make	Peugeot 508 1.5 BHDi Allure Pa
Mileage	127959
First registration	28/06/2021
client availability date	22/04/2026
inspectionDate	06/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
135	Bumper Rear // Replace & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
202	Rocker Panel Right // Painting	N
13	Bumper Front // Painting	N
63	Wing Front Left // Painting	Y
113	Wing Rear Left // Painting	Y
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch




Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Replace & Painting-scratch



Rocker Panel Right // Painting-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch