

# INSPECTION REPORT




End of contract

## GENERAL INFO

File	308745
License plate	2BSG029
Vehicle identification number	TMBJH9NP3N7032544
Dossier	2021 123 086
Make	Skoda Sup.Comb.TDi 150 Clever+
Mileage	212313
First registration	04/03/2022
client availability date	20/03/2026
inspectionDate	25/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
193	Door Rear Right // Painting	N
211	Door Front Right // Smart Repair Medium	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N

## Damage Pictures



Damage within Renta-norm-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Polish-scratch



Wing Rear Left // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Polish-scratch




Bumper Front // Painting-scratch




Wheel Alloy Front Right // Repair-scratch




Door Front Right // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-bad repair



Bumper Rear // Painting-bad repair



Windshield // Repair-cracked