

INSPECTION REPORT



End of contract

GENERAL INFO

File	315426
License plate	JK2026
Vehicle identification number	VXKUSHPY8RW075011
Dossier	2024263005
Make	Opel Mokka 1.2T 136 AT Edition
Mileage	41072
First registration	22/04/2025
client availability date	15/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	Y
134	Bumper Rear // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Wing Rear Left / Trim / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Left // Smart Repair Medium-dent



Bumper Rear // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Interior Cleaning // Small-stain