

INSPECTION REPORT

End of contract

GENERAL INFO

File	314114
License plate	2CCT857
Vehicle identification number	VSSZZZKJZNR108388
Dossier	2022 045 019
Make	Seat Arona 1.0 81kW Move DSG
Mileage	117493
First registration	08/06/2022
client availability date	08/06/2026
inspectionDate	10/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
31	Front Bonnet // Smart Repair Small	Y
40	Windshield // Repair	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch




Door Rear Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Bonnet // Smart Repair Small-dent



Windshield // Repair-glass damage



Interior Cleaning // Small-stain