

INSPECTION REPORT



End of contract

GENERAL INFO

File	318468
License plate	1YMV778
Vehicle identification number	VF3MCYHZJLS230805
Dossier	2020 055 122
Make	Peugeot 5008 1.5BHDi 96kW Acti
Mileage	214962
First registration	22/10/2020
client availability date	27/07/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	N
124	Light / Rear left / Replace	N
16	Bumper Front // Polish	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
28	Front / Calendar / Replace	Y
75	Side View Mirror Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
162	Roof // Painting	Y
184	Wing Rear Right // Repair & Painting	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	Y
271	Bumper Front / Trim Left / Replace	Y
273	Bumper Front / Grid Left / Replace	Y
274	Bumper Front / Grid Central / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
553	Central Console / Gear Lever / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch




Bumper Front // Polish-scratch



Wheel Alloy Front Right // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Door Rear Left // Repair & Painting-dent




Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Wing Rear Right // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-cracked



Front / Calendar / Replace-Chemical reaction



Roof // Painting-Chemical reaction



Interior Cleaning // Small-stain



Interior // Repair 1-worn



Central Console / Gear Lever / Replace-worn



Bumper Front / Trim Left / Replace-bad position




Bumper Front / Lower Cover Not Painted / Replace-bad position



Bumper Front / Grid Left / Replace-bad position



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Light / Rear left / Replace-scratch



Wing Rear Left // Painting-scratch