

INSPECTION REPORT

End of contract

GENERAL INFO

File	312603
License plate	2ADP497
Vehicle identification number	YV1XZBWVFM2559122
Dossier	2020317058
Make	Volvo XC40 T4 PHEV Inscript.Gt
Mileage	114950
First registration	01/03/2021
client availability date	13/05/2026
inspectionDate	29/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
28	Front / Calendar / Replace	N
33	Front Bonnet // Repair & Painting	N
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	N
190	Door Rear Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures




Side View Mirror Right // Painting-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Bumper Front / Spoiler / Replace-dent



Door Rear Right // Smart Repair Small-dent



Bumper Front // Repair & Painting-scratch + dent



Rear Bonnet // Polish-scratch



Light / Rear Right / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch






Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Front / Calendar / Replace-scratch



Front Bonnet // Repair & Painting-scratch + dent



Wing Front right // Polish-scratch



Door Front Right // Polish-scratch