

INSPECTION REPORT



End of contract

GENERAL INFO

File	321256
License plate	2CJY763
Vehicle identification number	W1K5M8GB4PN333417
Dossier	2021 196 050
Make	Mercedes CLA SB 250 e Bus.Solu
Mileage	123945
First registration	18/08/2022
client availability date	04/09/2026
inspectionDate	09/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
210	Door Front Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	N
336	Tyre Rear Right // Replace	Y

Damage Pictures



Door Front Right // Smart Repair Small-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Tyre Rear Right // Replace-worn