

INSPECTION REPORT



End of contract


GENERAL INFO

File	315704
License plate	PH9520
Vehicle identification number	VR3ECYHZRLJ838581
Dossier	2020 176 019
Make	Peugeot Rifter MWD HDi130 L AI
Mileage	46747
First registration	30/04/2021
client availability date	18/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
87	Door Front Left / Trim / Replace	N
98	Rocker Panel Left / Cover Not Painted / Replace	N
13	Bumper Front // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	N
140	Back Side // Smart Repair Medium	N
154	Rear Bonnet // Repair & Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
214	Door Front Right // Repair & Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	N
318	Flat Tyre Kit // Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	N
551	Central Console // Repair	N
561	Dashboard // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Door Front Right // Repair & Painting-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-bad repair



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Back Side // Smart Repair Medium-scratch



Light / Rear left / Replace-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Dashboard // Repair-scratch



Central Console // Repair-scratch



Wing Rear Right // Repair & Painting-dent



Door Front Left // Smart Repair Small-dent



Wing Rear Left // Repair & Painting-dent



Door Front Left / Trim / Replace-scratch + dent



Rocker Panel Left / Cover Not Painted / Replace-scratch +
dent