

INSPECTION REPORT

End of contract


GENERAL INFO

File	319897
License plate	97401
Vehicle identification number	TMBGF7NYXPF034295
Dossier	2023191023
Make	Skoda Enyaq Coupe 82kWh 80x
Mileage	99499
First registration	09/08/2023
client availability date	10/08/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	Y
216	Door Front Right // Polish	Y
233	Wing Front right // Painting	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Rear Bonnet // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Polish-scratch



Wing Front right // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Rear Left // Repair-scratch




Wing Rear Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Bumper Rear // Painting-bad repair



Door Front Left // Painting-bad repair



Door Rear Left // Painting-bad repair