



ARVAL
BNP PARIBAS GROUP

2ABD037

INSPECTION REPORT




End of contract

GENERAL INFO

File	314417
License plate	2ABD037
Vehicle identification number	W1N2476101W087131
Dossier	2020 190 084
Make	Mercedes GLB 180d Business Sol
Mileage	144492
First registration	05/02/2021
client availability date	09/06/2026
inspectionDate	12/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
191	Door Rear Right // Smart Repair Medium	N
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
217	Door Front Right / Trim / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
840	Interior Cleaning // Large	N

Damage Pictures



Door Front Right // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Smart Repair Medium-scratch




Wing Rear Right // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Front Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Repair-cracked



Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Large-stain



Dashboard / Steering Wheel / Replace-worn



Door Front Right / Trim / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Bumper Rear // Painting-scratch





Rear Left Door Interior Coating // Repair-scratch



Bumper Front // Painting-scratch



Rear Right Door Interior Coating // Repair-scratch





Rocker Panel Right // Smart Repair Medium-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch