

INSPECTION REPORT


End of contract

GENERAL INFO

File	305850
License plate	2AGH751
Vehicle identification number	ZARPAGBX6L7C83491
Dossier	2021077082
Make	Alfa Romeo Stelvio 2.2D 160 Su
Mileage	83356
First registration	25/03/2021
client availability date	31/03/2026
inspectionDate	02/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
138	Bumper Rear / Lower Cover Not Painted / Replace	N
148	Back Side / Reflector R / Replace	N
258	Towing Cover Rear // Replace	N
75	Side View Mirror Left // Polish	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
84	Door Front Left // Repair & Painting	Y
98	Rocker Panel Left / Cover Not Painted / Replace	N
104	Door Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
222	Side View Mirror Right // Painting	Y
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
452	Seat Rear Right / Bottom Coating / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
556	Central Console / Cover Armrest / Replace Cover Armrest	N
560	Interior / A Pillar Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures



Damage within Renta-norm-



Interior // Repair 1-Incinerated



Interior / A Pillar Cover / Replace-Incinerated




Trunk Compartment / Boot Cover / Replace-missing



Wheel Two Tone Front Right // Repair-Chemical reaction





Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Rear Right // Repair-Chemical reaction




Wheel Two Tone Front Left // Repair-Chemical reaction




Central Console / Cover Armrest / Replace Cover
Armrest-tear




Side View Mirror Right // Painting-Chipped paint



Dashboard / Steering Wheel / Replace-scratch



Seat Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Side View Mirror Left // Polish-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Rocker Panel Left / Cover Not Painted / Replace-scratch



Seat Rear Right / Bottom Coating / Replace-dent



Door Front Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Towing Cover Rear // Replace-scratch



Back Side / Reflector R / Replace-cracked