

INSPECTION REPORT



End of contract

GENERAL INFO

File	322337
License plate	2BUF054
Vehicle identification number	W1K1186121N300798
Dossier	2021 319 050
Make	Mercedes CLA SB 200 d Bus.Solu
Mileage	191609
First registration	24/03/2022
client availability date	16/09/2026
inspectionDate	25/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
91	Rocker Panel Left // Smart Repair Medium	N
161	Roof // Smart Repair Medium	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Seat Front Left // Repair-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Interior // Repair 1-scratch





Trunk Compartment / Side Cover Left / Replace-scratch



Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent





Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Front Right // Repair-Chipped paint



Wheel Two Tone Rear Right // Repair-Chipped paint