

INSPECTION REPORT


End of contract


GENERAL INFO

File	313033
License plate	2AMR723
Vehicle identification number	ZARPAGPX7M7D13981
Dossier	2020 289 047
Make	Alfa Romeo Stelvio 2.2D 160 Sp
Mileage	95083
First registration	17/05/2021
client availability date	08/06/2026
inspectionDate	15/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y

Damage Pictures



Bumper Front // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Front Left // Repair-Chipped paint