

INSPECTION REPORT


End of contract

GENERAL INFO

File	307112
License plate	1YWD412
Vehicle identification number	TMBAG7NX9MY079500
Dossier	2020 281 052
Make	Skoda Octavia 2.0TDI 85kW Styl
Mileage	62132
First registration	04/01/2021
client availability date	09/03/2026
inspectionDate	12/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
654	Lettering Removal 15min	N
14	Bumper Front // Repair & Painting	N
38	Front Bonnet / Insulation / Replace	N
61	Wing Front Left // Smart Repair Medium	N
91	Rocker Panel Left // Smart Repair Medium	N
152	Rear Bonnet // Smart Repair Large	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
540	Interior // Repair 1	N

Damage Pictures



Damage within Renta-norm-



Interior // Repair 1-cracked



Front Bonnet / Insulation / Replace-tear



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Rear Bonnet // Smart Repair Large-scratch



Wing Front Left // Smart Repair Medium-scratch + dent






Bumper Front // Repair & Painting-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Right // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Lettering Removal 15min-Remainder stickers