

# INSPECTION REPORT

**End of contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 320022                         |
| License plate                 | 2CPW378                        |
| Vehicle identification number | TMAJD811BNJ131166              |
| Dossier                       | 2022035005                     |
| Make                          | Hyundai Tuc.T-GDi Hyb.169kW Fe |
| Mileage                       | 49813                          |
| First registration            | 12/10/2022                     |
| client availability date      | 11/08/2026                     |
| inspectionDate                | 20/08/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | Y       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                           | Acceptable |
|---------|------------------------------------------------|------------|
| 194     | Door Rear Right // Repair & Painting           | N          |
| 197     | Door Rear Right / Trim / Replace               | N          |
| 11      | Bumper Front // Smart Repair Medium            | N          |
| 63      | Wing Front Left // Painting                    | N          |
| 67      | Wing Front Left / Trim / Replace               | N          |
| 86      | Door Front Left // Polish                      | N          |
| 100     | Door Rear Left // Smart Repair Small           | Y          |
| 118     | Wing Rear Left / Fuel Cover / Replace          | Y          |
| 139     | Bumper Rear / Spoiler / Replace                | N          |
| 183     | Wing Rear Right // Painting                    | Y          |
| 211     | Door Front Right // Smart Repair Medium        | Y          |
| 234     | Wing Front right // Repair & Painting          | Y          |
| 340     | Wheel Two Tone Front Right // Repair           | Y          |
| 346     | Tyre Front Right // Replace                    | N          |
| 533     | Trunk Compartment / Side Cover Right / Replace | Y          |

## Damage Pictures



Wing Rear Right // Painting-scratch



Bumper Rear / Spoiler / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Wing Front right // Repair & Painting-rust



Tyre Front Right // Replace-tear



Wing Rear Left / Fuel Cover / Replace-scratch



Door Rear Left // Smart Repair Small-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Wing Front Left / Trim / Replace-scratch



Door Front Left // Polish-scratch



Wing Front Left // Painting-scratch



Bumper Front // Smart Repair Medium-scratch