

INSPECTION REPORT

End of contract


GENERAL INFO

File	307996
License plate	1YXK625
Vehicle identification number	TMBJN7NPXM7041639
Dossier	2020 247 082
Make	Skoda Sup.Comb.TSI 150 Ambitio
Mileage	89475
First registration	21/01/2021
client availability date	17/03/2026
inspectionDate	31/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
114 Wing Rear Left // Repair & Painting		Y
184 Wing Rear Right // Repair & Painting		N

Damage Pictures



Damage within Renta-norm-



Wing Rear Left // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent