

INSPECTION REPORT


End of contract

GENERAL INFO

File	318382
License plate	2CDJ608
Vehicle identification number	LYVUZK9VDNB055929
Dossier	2021343419
Make	Volvo XC60 B4 P Momentum Pro G
Mileage	84430
First registration	13/06/2022
client availability date	03/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
87	Door Front Left / Trim / Replace	N
107	Door Rear Left / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
801	See External Expertise	N
12	Bumper Front // Smart Repair Large	N
60	Wing Front Left // Smart Repair Small	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
194	Door Rear Right // Repair & Painting	N
214	Door Front Right // Repair & Painting	Y
236	Wing Front right // Polish	Y
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Wing Front Left // Smart Repair Small-dent



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Two Tone Front Right // Repair-Chemical reaction



Bumper Front // Smart Repair Large-scratch



Wing Front right // Polish-scratch



Wing Rear Left // Repair & Painting-scratch





Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Rear Bonnet // Polish-scratch





Bumper Rear // Painting-scratch



Door Rear Left / Trim / Replace-scratch



Door Front Left / Trim / Replace-scratch



See External Expertise-Splashes



Door Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch