

INSPECTION REPORT


End of contract

GENERAL INFO

File	320073
License plate	2AVF151
Vehicle identification number	VF3M4DGZUMS098414
Dossier	2021 196 077
Make	Peugeot 3008 PHEV 165kW Allure
Mileage	185702
First registration	02/08/2021
client availability date	19/08/2026
inspectionDate	21/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	









DAMAGES

Damages	Type	Acceptable
131	Bumper Rear // Smart Repair Medium	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
83	Door Front Left // Painting	Y
101	Door Rear Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
543	Interior // Ionization Odor	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures




Seat Front Left / Bottom Coating / Replace-Incinerated



Interior Cleaning // Small-stain



Wheel Two Tone Rear Right // Repair-scratch



Door Front Right // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch





Wheel Two Tone Front Left // Repair-scratch



Wing Rear Left / Trim / Replace-scratch



Door Rear Left // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent