

INSPECTION REPORT



End of contract


GENERAL INFO

File	320034
License plate	2BAY847
Vehicle identification number	W1N1671171A541653
Dossier	2021 063 131
Make	Mercedes GLE 350 de 4M
Mileage	268600
First registration	14/09/2021
client availability date	18/08/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
274	Bumper Front / Grid Central / Replace	N
33	Front Bonnet // Repair & Painting	N
41	Windshield // Replace	Y
66	Wing Front Left // Polish	Y
83	Door Front Left // Painting	Y
93	Rocker Panel Left // Repair & Painting	Y
106	Door Rear Left // Polish	Y
117	Wing Rear Left / Trim / Replace	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
165	Roof // Polish	Y
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
216	Door Front Right // Polish	Y
233	Wing Front right // Painting	N
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
422	Seat Front Right / Bottom Coating / Replace	Y
540	Interior // Repair 1	Y
569	Dashboard / Steering Wheel / Replace	Y

594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
-----	---	---

Damage Pictures



Wing Front right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Wing Front Left // Polish-scratch



Windshield // Replace-scratch




Wing Rear Right // Polish-scratch



Bumper Rear // Repair & Painting-scratch + dent




Door Rear Right // Repair & Painting-scratch + dent





Roof // Polish-scratch + dent



Roof // Polish-scratch



Rocker Panel Left // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Seat Front Left // Repair-cracked



Dashboard / Steering Wheel / Replace-worn



Seat Front Right / Bottom Coating / Replace-worn



Seat Front Left / Bottom Coating / Replace-worn



Door Front Right // Polish-stone chipping



Bumper Rear / Lower Cover Not Painted / Replace-bad position



Interior // Repair 1-hole




Wing Rear Right / Trim / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Roof // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Grid Central / Replace-scratch