

INSPECTION REPORT

End of contract

GENERAL INFO

File	321359
License plate	2CMZ205
Vehicle identification number	VR3FCYHZTNY578519
Dossier	2022 045 116
Make	Peugeot 308 SW 1.5BHDi 130 GT
Mileage	142154
First registration	22/09/2022
client availability date	07/09/2026
inspectionDate	21/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
234	Wing Front right // Repair & Painting	N
891	Lettering Removal 15min	N
18	Bumper Front / Spoiler / Replace	N
33	Front Bonnet // Repair & Painting	N
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	Y
82	Door Front Left // Smart Repair Large	N
93	Rocker Panel Left // Repair & Painting	N
133	Bumper Rear // Painting	Y
139	Bumper Rear / Spoiler / Replace	Y
194	Door Rear Right // Repair & Painting	Y
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
310	Wheel Two Tone Front Left // Repair	N
318	Flat Tyre Kit // Replace	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
431	Seat Rear Left // Repair	N
540	Interior // Repair 1	N
551	Central Console // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Windshield // Replace-scratch




Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Seat Rear Left // Repair-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Bumper Front / Spoiler / Replace-scratch + dent



Rocker Panel Left // Repair & Painting-scratch + dent



Door Front Left // Smart Repair Large-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Flat Tyre Kit // Replace-missing



Wheel Two Tone Front Left // Repair-Chemical reaction



Interior // Repair 1-tear



Front Bonnet / Insulation / Replace-tear



Tyre Rear Right // Replace-tear



Seat Front Left / Bottom Coating / Replace-worn



Central Console // Repair-scratch



Bumper Front / Trim Left / Replace-scratch



Wing Front right // Repair & Painting-scratch + dent



Bumper Front // Painting-scratch



Lettering Removal 15min-