

INSPECTION REPORT

End of contract

GENERAL INFO

File	306112
License plate	1YQA300
Vehicle identification number	VR3F4DGZTLY039660
Dossier	2020198007
Make	Peugeot 508SW 1.6 225 PHEV GT
Mileage	61771
First registration	30/10/2020
client availability date	24/02/2026
inspectionDate	26/02/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
266	Foglight Rear // Replacement	N
13	Bumper Front // Painting	N
60	Wing Front Left // Smart Repair Small	Y
72	Side View Mirror Left // Painting	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
153	Rear Bonnet // Painting	N
157	Rear Bonnet / Trim / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
222	Side View Mirror Right // Painting	N
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-



Bumper Front // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Left // Painting-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear Right / Replace-scratch



Wing Front right // Polish-scratch



Rear Bonnet // Painting-scratch



Rear Bonnet / Trim / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Polish-scratch



Wing Front Left // Smart Repair Small-scratch




Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Smart Repair Medium-dent



Interior Cleaning // Small-dirty



Door Front Right // Repair & Painting-scratch + dent



Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Rear // Repair & Painting-scratch + dent



Foglight Rear // Replacement-cracked



Bumper Rear / Spoiler / Replace-scratch