

INSPECTION REPORT

End of contract

GENERAL INFO

| | |
|-------------------------------|--------------------------------|
| File | 313743 |
| License plate | XY4779 |
| Vehicle identification number | VR3USHNSSNJ662274 |
| Dossier | 2021342035 |
| Make | Peugeot 2008 1.2 PT 130 Allure |
| Mileage | 44342 |
| First registration | 26/07/2022 |
| client availability date | 26/05/2026 |
| inspectionDate | 29/05/2026 |

CHECK POINTS

| Description | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate | | N | |
| Registration Part 2 | | N | |
| Keys | 2 | Y | |
| Spare wheel | | N | |
| Towbar (+keys) | | N | |
| Certificate of conformity | | N | |
| Registration certificate | | N | |
| Repair kit | | Y | |
| RunOnFlat | | N | |
| Charging cable | | N | |
| Charge back wrong tyres | | N | |





DAMAGES

| Damages | Type | Acceptable |
|---------|---|------------|
| 131 | Bumper Rear // Smart Repair Medium | N |
| 138 | Bumper Rear / Lower Cover Not Painted / Replace | N |
| 187 | Wing Rear Right / Trim / Replace | N |
| 84 | Door Front Left // Repair & Painting | N |
| 100 | Door Rear Left // Smart Repair Small | Y |
| 156 | Rear Bonnet // Polish | Y |
| 157 | Rear Bonnet / Trim / Replace | Y |
| 161 | Roof // Smart Repair Medium | Y |
| 175 | Light / Rear Right On Rear Bonnet / Replace | N |
| 183 | Wing Rear Right // Painting | N |
| 194 | Door Rear Right // Repair & Painting | N |
| 210 | Door Front Right // Smart Repair Small | Y |
| 214 | Door Front Right // Repair & Painting | Y |
| 217 | Door Front Right / Trim / Replace | N |
| 233 | Wing Front right // Painting | N |
| 310 | Wheel Two Tone Front Left // Repair | N |
| 540 | Interior // Repair 1 | N |
| 594 | Trunk Lid Interior Coating / Complete Panel / Replace | Y |
| 860 | Interior Cleaning // Small | N |

Damage Pictures



Rear Bonnet // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Door Front Right / Trim / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Smart Repair Small-dent




Roof // Smart Repair Medium-dent



Door Front Left // Repair & Painting-dent



Door Front Right // Repair & Painting-dent



Rear Bonnet / Trim / Replace-dent



Door Rear Right // Repair & Painting-dent



Wing Rear Right // Painting-bad repair



Wing Front right // Painting-bad repair



Interior // Repair 1-cracked



Interior Cleaning // Small-stain



Bumper Rear // Smart Repair Medium-scratch



Wing Rear Right / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch