

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	280506
License plate	2CTJ215
Vehicle identification number	WBA6V110405W02738
Dossier	2022 110 102
Make	BMW 216i GranTourer 80kW
Mileage	65358.00
First registration	21/11/2022
	07/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
680	Keys Detachable Towing Hook //	N

Damage Pictures



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Painting-scratch + dent