

INSPECTION REPORT




End of contract

GENERAL INFO

File	318202
License plate	2CAQ041
Vehicle identification number	VF3MRHNSMNS070203
Dossier	2021274074
Make	Peugeot 3008 1.2PTech 96kW GT
Mileage	95746
First registration	12/05/2022
client availability date	24/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
18	Bumper Front / Spoiler / Replace	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
110	Wing Rear Left // Smart Repair Small	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
154	Rear Bonnet // Repair & Painting	N
180	Wing Rear Right // Smart Repair Small	N
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
282	Bumper Rear / Trim Center / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Wing Rear Right / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Front Bonnet // Polish-scratch



Rear Bonnet // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Small-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Left // Smart Repair Small-scratch + dent



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Smart Repair Medium-scratch