

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307394
License plate	2ATL343
Vehicle identification number	KMHC851CGLU218193
Dossier	2021 161 069
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	160691
First registration	09/07/2021
client availability date	05/03/2026
inspectionDate	11/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
27	Front / Logo / Replace	N
28	Front / Calendar / Replace	N
63	Wing Front Left // Painting	N
72	Side View Mirror Left // Painting	N
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	N
93	Rocker Panel Left // Repair & Painting	N
15	Bumper Front // Replace & Painting	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
153	Rear Bonnet // Painting	N
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
210	Door Front Right // Smart Repair Small	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
551	Central Console // Repair	N
553	Central Console / Gear Lever / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

614	Front Left Door Interior Coating // Replace Completely	N
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N
774	Interior / Side Cover rear Seat / Replace	N



### Damage Pictures



Damage within Renta-norm-scratch



Bumper Front / Spoiler / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Light / Rear left / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Central Console // Repair-scratch



Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Front Left Door Interior Coating // Replace Completely-scratch + dent



Bumper Front // Replace & Painting-cracked




Central Console / Gear Lever / Replace-cracked



Interior // Repair 1-Incinerated





Seat Front Left / Bottom Coating / Replace-Incinerated



Rear Bonnet // Painting-Chemical reaction



Front Bonnet // Painting-Chemical reaction



Interior // Repair 2-tear



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Front / Logo / Replace-cracked



Front / Calendar / Replace-cracked



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Repair & Painting-scratch + dent



Side View Mirror Left // Painting-scratch



Door Front Left / Trim / Replace-scratch



Wing Front Left // Painting-scratch