

INSPECTION REPORT


End of contract

GENERAL INFO

File	319970
License plate	2BRT831
Vehicle identification number	TMBJJ7NS3N8030719
Dossier	2021 167 086
Make	Skoda Kod.2.0CRTDI 110kW Cleve
Mileage	79850
First registration	28/02/2022
client availability date	10/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
67	Wing Front Left / Trim / Replace	N
133	Bumper Rear // Painting	N
161	Roof // Smart Repair Medium	N
162	Roof // Painting	N
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N


Damage Pictures



Bumper Front // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Rear // Painting-scratch



Wing Rear Right // Polish-scratch




Door Rear Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Roof // Smart Repair Medium-dent



Roof // Painting-Chemical reaction