



ARVAL
BNP PARIBAS GROUP

MA6806

INSPECTION REPORT


End of contract

GENERAL INFO

File	321179
License plate	MA6806
Vehicle identification number	YV1UZH1V0R1828843
Dossier	2024003005
Make	Volvo XC60 T6 350PHEV AWD PL.D
Mileage	34368
First registration	22/01/2024
client availability date	31/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
194	Door Rear Right // Repair & Painting	Y
213	Door Front Right // Painting	Y
274	Bumper Front / Grid Central / Replace	Y

Damage Pictures



Door Front Right // Painting-scratch



Bumper Rear // Painting-scratch



Bumper Front / Grid Central / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent