

INSPECTION REPORT


End of contract

GENERAL INFO

File	310431
License plate	EB7710
Vehicle identification number	VSSZZZKJ9RR064911
Dossier	2023215020
Make	Seat Ibiza 1.0eTSi 110 Xcellen
Mileage	51091
First registration	05/02/2024
client availability date	13/04/2026
inspectionDate	15/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	N
81	Door Front Left // Smart Repair Medium	Y
136	Bumper Rear // Polish	Y
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Bumper Rear // Polish-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Interior Cleaning // Small-stain