

INSPECTION REPORT







End of contract

GENERAL INFO

File	314116
License plate	2CCT872
Vehicle identification number	VSSZZZKJZNR091496
Dossier	2022045030
Make	Seat Arona 1.0 81kW Move DSG
Mileage	106796
First registration	08/06/2022
client availability date	08/06/2026
inspectionDate	10/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	N
67	Wing Front Left / Trim / Replace	Y
75	Side View Mirror Left // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
193	Door Rear Right // Painting	Y
272	Bumper Front / Trim Right / Replace	N


Damage Pictures



Bumper Front // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Side View Mirror Left // Polish-scratch



Door Rear Right // Painting-scratch



Bumper Rear // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Bumper Front / Spoiler / Replace-dent



Wing Front Left / Trim / Replace-bad position