

INSPECTION REPORT




End of contract

GENERAL INFO

File	309213
License plate	2ABK842
Vehicle identification number	TMBJJ7NX7MY108042
Dossier	2020 328 078
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	149014
First registration	09/02/2021
client availability date	30/03/2026
inspectionDate	07/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
66	Wing Front Left // Polish	Y
72	Side View Mirror Left // Painting	Y
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
110	Wing Rear Left // Smart Repair Small	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
151	Rear Bonnet // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch




Side View Mirror Left // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch




Bumper Front // Smart Repair Large-scratch




Wheel Alloy Front Right // Repair-scratch




Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Polish-scratch



Wing Rear Left // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior // Repair 1-Incinerated



Rear Bonnet // Smart Repair Medium-Chemical reaction



Seat Front Left / Rear Coating / Replace-worn