

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	304344
License plate	2CLM392
Vehicle identification number	W1K5M8GB5PN339890
Dossier	2022 055 079
Make	Mercedes CLA SB 250 e Business
Mileage	130330
First registration	06/09/2022
client availability date	26/02/2026
inspectionDate	03/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
84	Door Front Left // Repair & Painting	N
93	Rocker Panel Left // Repair & Painting	N
110	Wing Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	N
154	Rear Bonnet // Repair & Painting	N
186	Wing Rear Right // Polish	Y
203	Rocker Panel Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
433	Seat Rear Left / Rear Coating / Replace	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Rear Bonnet // Repair & Painting-scratch





Bumper Rear // Painting-scratch





Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Polish-scratch



Door Front Right // Smart Repair Small-dent




Wing Rear Left // Smart Repair Small-dent






Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent




Rocker Panel Left // Repair & Painting-scratch + dent




Door Front Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-dirty



Seat Rear Left / Rear Coating / Replace-tear



Seat Front Left / Rear Coating / Replace-worn