

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	308674
License plate	1YXY734
Vehicle identification number	TMBJJ7NS8M8035493
Dossier	2020 302 068
Make	Skoda Kod.2.0CRTDI 110kW Style
Mileage	143716
First registration	27/01/2021
client availability date	19/03/2026
inspectionDate	31/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
67	Wing Front Left / Trim / Replace	N
81	Door Front Left // Smart Repair Medium	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
161	Roof // Smart Repair Medium	Y
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	N
190	Door Rear Right // Smart Repair Small	Y
210	Door Front Right // Smart Repair Small	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Door Front Right // Smart Repair Small-scratch



Door Rear Right // Smart Repair Small-scratch




Wing Rear Right / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Trunk Lid Interior Coating / MDF Rear Right / Replace-scratch



Roof // Smart Repair Medium-dent



Interior Cleaning // Small-stain



Trunk Lid Interior Coating / MDF Rear Left / Replace-



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Smart Repair Medium-scratch