

INSPECTION REPORT


End of contract

GENERAL INFO

File	320920
License plate	LL9718
Vehicle identification number	W1NKM5GB7PF037886
Dossier	2023011006
Make	Mercedes GLC 300 e 4M Business
Mileage	98013
First registration	11/05/2023
client availability date	26/08/2026
inspectionDate	28/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
41	Windshield // Replace	Y
113	Wing Rear Left // Painting	Y
159	Rear Bonnet / Rear Window / Replace	N
190	Door Rear Right // Smart Repair Small	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left // Painting-scratch



Bumper Front // Painting-scratch



Door Rear Right // Smart Repair Small-dent



Windshield // Replace-glass damage