



ARVAL
BNP PARIBAS GROUP

TQ7979

INSPECTION REPORT

End of contract

GENERAL INFO

File	316604
License plate	TQ7979
Vehicle identification number	W1KAF0EB5PR081926
Dossier	2021308003
Make	Mercedes C 220d 200 AMG Line A
Mileage	134106
First registration	23/01/2023
client availability date	30/06/2026
inspectionDate	02/07/2026



CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	



DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
14	Bumper Front // Repair & Painting	N
272	Bumper Front / Trim Right / Replace	N
32	Front Bonnet // Painting	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
80	Door Front Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
183	Wing Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
233	Wing Front right // Painting	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Front Bonnet // Painting-stone chipping




Wing Front right // Painting-stone chipping



Door Front Right // Smart Repair Small-scratch



Wheel Two Tone Rear Right // Repair-scratch




Bumper Rear // Painting-scratch



Wing Rear Right // Painting-scratch



Wing Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Side View Mirror Right // Painting-scratch



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Trim Right / Replace-cracked