

INSPECTION REPORT

End of contract

GENERAL INFO

File	307472
License plate	2CXY899
Vehicle identification number	VXKUBYHTKN4422750
Dossier	2022 192 151
Make	Opel Corsa 1.5D 102 Edition
Mileage	27825
First registration	10/01/2023
client availability date	06/03/2026
inspectionDate	16/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
234	Wing Front right // Repair & Painting	N
191	Door Rear Right // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	N
203	Rocker Panel Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	N
213	Door Front Right // Painting	N
135	Bumper Rear // Replace & Painting	N
174	Light / Rear Right / Replace	N
225	Side View Mirror Right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N

Damage Pictures




Side View Mirror Right // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Rear // Replace & Painting-cracked



Light / Rear Right / Replace-scratch




Bumper Front // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent



Rocker Panel Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Smart Repair Medium-scratch



Door Front Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch