

INSPECTION REPORT



End of contract


GENERAL INFO

File	319783
License plate	GD6461
Vehicle identification number	W1NKM0FB6RF170209
Dossier	2023081005
Make	Mercedes GLC 220d 197 Busin.Li
Mileage	79025
First registration	02/04/2024
client availability date	07/08/2026
inspectionDate	13/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
244	Light / Front Right / Replace	N
274	Bumper Front / Grid Central / Replace	N
35	Front Bonnet // Polish	Y
41	Windshield // Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
346	Tyre Front Right // Replace	N


Damage Pictures




Windshield // Replace-cracked



Tyre Front Right // Replace-tear



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent




Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch




Door Rear Left // Polish-scratch



Front Bonnet // Polish-scratch



Light / Front Right / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-cracked