

INSPECTION REPORT



End of contract

GENERAL INFO

File	320510
License plate	2CCB151
Vehicle identification number	TMBJF7NU0N5056702
Dossier	2021 147 126
Make	Skoda Karoq 2.0TDi 85kW Clever
Mileage	64811
First registration	30/05/2022
client availability date	26/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
18	Bumper Front / Spoiler / Replace	N
67	Wing Front Left / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
72	Side View Mirror Left // Painting	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
153	Rear Bonnet // Painting	Y
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	N
213	Door Front Right // Painting	Y
321	Wheel Alloy Rear Left // Repair	N
540	Interior // Repair 1	N
541	Interior // Repair 2	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Smart Repair Medium-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Door Rear Right / Trim / Replace-scratch



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent




Interior // Repair 1-cracked



Interior Cleaning // Small-stain



Interior // Repair 2-hole



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Rear Left Door Interior Coating // Repair-scratch



Side View Mirror Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Bumper Front / Spoiler / Replace-scratch