

INSPECTION REPORT

End of contract

GENERAL INFO

File	309806
License plate	2AAN734
Vehicle identification number	TMBJJ7NX1MY103208
Dossier	2020 266 108
Make	Skoda Oct.Com.2.0TDI 110kW Sty
Mileage	84971
First registration	02/02/2021
client availability date	02/04/2026
inspectionDate	14/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
196	Door Rear Right // Polish	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Bumper Rear // Painting-scratch



Door Rear Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch