

INSPECTION REPORT



End of contract

GENERAL INFO

File	320475
License plate	2BBV409
Vehicle identification number	VXKUSHNEKMW039722
Dossier	2021 256 001
Make	Opel Mokka 1.2 100 s/s Edition
Mileage	81898
First registration	23/09/2021
client availability date	26/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
117	Wing Rear Left / Trim / Replace	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
16	Bumper Front // Polish	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	Y
102	Door Rear Left // Smart Repair Large	N
163	Roof // Repair & Painting	N
191	Door Rear Right // Smart Repair Medium	Y
201	Rocker Panel Right // Smart Repair Medium	N
211	Door Front Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
233	Wing Front right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
551	Central Console // Repair	Y
621	Front Right Door Interior Coating // Repair	Y
634	Rear Left Door Interior Coating // Replace Completely	N
840	Interior Cleaning // Large	N

Damage Pictures



Roof // Repair & Painting-scratch + dent



Bumper Front // Polish-bad repair



Interior Cleaning // Large-stain



Central Console // Repair-worn



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Door Front Left / Trim / Replace-scratch



Front Right Door Interior Coating // Repair-scratch



Side View Mirror Right // Painting-scratch



Wing Front right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch




Door Rear Left // Smart Repair Large-dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Right // Smart Repair Medium-scratch + dent



Rear Left Door Interior Coating // Replace Completely-scratch + dent



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent