

# INSPECTION REPORT

End of contract


## GENERAL INFO

File	309028
License plate	2FXK434
Vehicle identification number	VXKFRHNP9R1024080
Dossier	2023356291
Make	Opel Astra ST 1.2 81kW Edition
Mileage	6035
First registration	26/09/2024
client availability date	25/03/2026
inspectionDate	26/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
73	Side View Mirror Left // Replace Not Painted	N
78	Side View Mirror Left / Direction Indicator / Replace	N
183	Wing Rear Right // Painting	N
193	Door Rear Right // Painting	N
13	Bumper Front // Painting	Y
35	Front Bonnet // Polish	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
165	Roof // Polish	Y
203	Rocker Panel Right // Repair & Painting	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
591	Trunk Lid Interior Coating // Repair	Y
883	Key Price Range 2 //	N


## Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch




Roof // Polish-scratch



Wing Rear Left // Painting-scratch



Trunk Lid Interior Coating // Repair-scratch



Front Bonnet // Polish-scratch



Rocker Panel Right // Repair & Painting-dent



Bumper Rear // Painting-bad repair



Bumper Front // Painting-stone chipping



Side View Mirror Left // Replace Not Painted-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch