

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306614
License plate	2BLX793
Vehicle identification number	YV1ZWK5VDN2473815
Dossier	2021344003
Make	Volvo V60 B4 D R-Design Gtr.
Mileage	126772
First registration	10/01/2022
client availability date	03/03/2026
inspectionDate	12/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
41	Windshield // Replace	N
151	Rear Bonnet // Smart Repair Medium	N
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
205	Rocker Panel Right // Polish	Y
257	Front / Towing Cover / Replace	N
258	Towing Cover Rear // Replace	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
421	Seat Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N

## Damage Pictures





Damage within Renta-norm-



Windshield // Replace-glass damage



Towing Cover Rear // Replace-missing



Front / Towing Cover / Replace-missing



Seat Front Left // Repair-tear



Rear Left Door Interior Coating // Repair-tear



Seat Front Left / Bottom Coating / Replace-worn



Rear Bonnet // Smart Repair Medium-N comf / out of order



Wing Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Seat Front Right // Repair-scratch



Rocker Panel Right // Polish-scratch



Bumper Rear // Repair & Painting-cracked



Bumper Rear / Spoiler / Replace-cracked