

INSPECTION REPORT

End of contract


GENERAL INFO

File	305550
License plate	2BSQ814
Vehicle identification number	VF3MCYHZMNS042114
Dossier	2021 320 053
Make	Peugeot 5008 1.5BHdi 96kW Allu
Mileage	37878
First registration	09/03/2022
client availability date	23/03/2026
inspectionDate	30/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
153	Rear Bonnet // Painting	Y
184	Wing Rear Right // Repair & Painting	N
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N

Damage Pictures



Bumper Front // Smart Repair Medium-scratch



Door Front Left // Painting-scratch



Door Rear Left // Painting-scratch



Bumper Rear // Polish-scratch




Rear Bonnet // Painting-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Rear Right // Smart Repair Medium-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent